



What's new in firmware 2.4 / 2.3 / 2.1 April 2010

- Link Margin function in Satellite – **very important in DVB-S2**
- Noise Margin function for Digital Terrestrial
- Minor bug correction (especially for V2.4)

All versions are fully compatible with SEFRAM 7860 family (7861, **7861HD**, 7862, **7862HD**, 7863, **7863HD**, 7865, **7865HD**, 7866, **7866HD**)

What was implemented in firmware 1.9 (January 2010)

- Improvement of echoes measurement in COFDM : 30dB true dynamic, 67 km for 8k, real time measurement
- Auto-power off of the instrument after 10mn (can be disabled by user)
- Improvement of constellation diagram : an integration period (1, 3, 10 et 30 seconds) has been added
- Improvement of COFDM measurement when an analogue channel is received in a digital multiplex
- Minor bug correction