



What's new in firmware 2.6 and 2.7 June/July 2010

- ➔ Improvement of Scope mode (in TV mode)
- ➔ Improvement of SatCR (inverto switch management)
- ➔ Minor bug correction
- ➔ Update of AB3 satellite parameters
- ➔ Improvement of echoes measurement (V2.7)

All versions are fully compatible with SEFRAM 7860 family (7861, **7861HD**, 7862, **7862HD**, 7863, **7863HD**, 7865, **7865HD**, 7866, **7866HD**)

What was implemented in previous firmware 2.5 / 2.4 / 2.3 / 2.1

- ➔ Link Margin function in Satellite – **very important in DVB-S2**
- ➔ Noise Margin function for Digital Terrestrial
- ➔ Minor bug correction (especially for V2.4 and V2.5)
- ➔ Improvement of digital picture quality (HD programs) – V2.5